


Section 1/4 11412 Twp 29S Rge 1E W

Date: 4-7-61



How was corner identified? BRASS CAP

Condition of corner: \_\_\_\_\_

Best route to reach corner: Road # 2942, Follow Telephone  
line to sec. line

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:

NO INFO ON B.T'S

Signed

#47 c

C. S. File No. 56410-57