


Section 1/4 12+13 Twp 29S Rge 1E W

Date: 4-6-61



How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: ROAD # 291J

56/40-5B
C.F. No.

Other Remarks:

BT'S SAME GWD NOTES

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Signed

#48