

Section 1/4 22423 Twp 29S Rge 1E W

Date: 7-18-61



How was corner identified? BYASS CAP

Condition of corner: BT's OK NO OTHER DATA

Best route to reach corner: ROAD* 2921

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:

Signed

#63 ✓
c

C.S. File No. 50/40-61