


Section 1/4 23424 Twp 29S

Rge 1E W

Date: 7-17-61



How was corner identified? BYASS CAP

Condition of corner: BT'S OK NO OTHER DATA

Best route to reach corner: ROAD #2921

U.S. File No. 50490-62

Other Remarks:

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Signed

# 64 ✓