

Section 12, 13, 7418 Twp 295 Rge 1E W

Date: 4-5-61



How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: ROAD* 291 J

C.S. File No. 56/40-64

Quadrant	NE	NW	SE	SW
Species & Size				
Dist. & Bearing				
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:

BT'S SAME AS IN
GLD NOTES.
Could be IN C.S.

J
#9 729-2E

Signed

129-1E
#66 c