

Section 14 144 15 Twp 29S Rge 1E W

Date: 5-20-48



How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: ROAD 2942 OR 291

C.S. FILE NO. 58140-66

Quadrant	NE	NW	SE	SW
Species & Size	SP 15"		DF 38"	
Dist. & Bearing	N22W 141K		S61E 201Ks	
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.	Tagged			

Other Remarks:
Sec. line MARKER ON
old Buckeye Cr. TRAIL

Signed #57 c