


Section 1/4 15422 Twp 29S Rge 1E W

Date: 5-20-48



How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: Road #291 - CORNER could
HAVE BEEN DESTROYED BY ROAD #291

C.S. File No. 56/40-69

Quadrant	NE	NW	SE	SW
Species & Size	<u>WF 6"</u>		<u>YEW 14"</u>	
Dist. & Bearing	<u>N11W. 181K</u>		<u>S34E. 321K</u>	
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.	<u>Tagged</u>			

Other Remarks:

Sec. line MAYKEY
ON THE OLD Buckeye
CY. TRAIL.

Signed

#55 ✓