

Section 16, 17, 20 & 21 Twp 29 S Rge 1 E W

Date: 4-30-47



How was corner identified? BRASS CAP

Condition of corner: _____

Best route to reach corner: Road # 2937

C. S. File No. 56/40-711

Quadrant	NE	NW	SE	SW
Species & Size	<u>I.C. 26"</u>	<u>DF 38"</u>	<u>DF. 38"</u>	<u>WF. 20"</u>
Dist. & Bearing	<u>N5E.341K</u>	<u>N14W.201K</u>	<u>S77E.291K</u>	<u>S51W.441K</u>
Condition of Scribe				
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.		<u>Tagged</u>		

Other Remarks:

Could lie in C.C.

Signed

#57c