

1-11-74

$\frac{1}{4}$ S 11 & S 12 T 315 R 6 W

FD: 3" X 3" CEDAR POST EXTENDING 24"
ABOVE GROUND

SCRIBED:

$\frac{1}{4}$ S 11 ON WEST FACE

$\frac{1}{4}$ S 12 ON EAST ~~FACE~~

POST IN EXCELLENT CONDITION

FROM WHICH?

34" D. FIR BEARS S 55° W 14⁰ FEET

INITIALS JM CHOPPED INTO BARK,

ALSO BEARS METAL G.L.D. LOCATION TAG

INITIALED BY MURDOCK & HAINES 9-24-76

NO VISIBLE SCALS

ROTTED-OUT FIR ROOT COLLAR BEARS

S 58° E 11² FEET

I DO NOT RENEW.

1-11-74

L.L.L.

P.L.E.

134 ✓

U.S. File No. 56/93-1

OK
JLL

C