

3-14-74

$\frac{1}{4}$

6

T215 R9W

FD:

A BRASS CAP MOUNTED ON AN IRON

PIPE. MARKED:

U.S. DEPT. OF INTERIOR
BUREAU OF LAND MANAGEMENT
CADASTRAL SURVEY

T215 R9W

$\frac{1}{4}$ 56

1966

ALSO FOUND A SANDSTONE ALONGSIDE
THE BRASS CAP WITH A " $\frac{1}{4}$ " CHISELED
ON THE NORTH FACE.

BOTH MONUMENTS WERE BURIED
UNDER ROAD EXCAVATION MATERIAL.

24 ✓

U.S. GEARING COMPANY
COLUMBIA, MISSOURI

Pat. of R.R.
CATERPILLAR

312

BEARING TREES:

25" NOW 30" D. FIR BEARS
 N52°E 117[±] FT WITH A WELL-
 HEALED BLAZE

THE NW BT, A HEMLOCK MARKED
 IN 1966 HAS SINCE FALLEN AND
 SLIP APPROX 30 FT DOWNHILL.

NEW BT:

A 14" D. FIR, BEARS N 72°W
 47[±] FT, SCRIBED " 1/4 56 CS BT "

NOTE: THIS CORNER LIES ON VERY STEEP
 SLOPE APPROX 100' NORTH OF AND
 50 FT LOWER THAN A GRAVEL-
 SURFACED LOGGING ROAD.

3-14-74

Larry Langley
 PETE EARLE

OK
 JEL