

3-19-74

$\frac{1}{4}$
10/11

T20S R10W

FD:

BRASS CAP MOUNTED ON AN IRON
PIPE

MARKED:

U.S. GENERAL LAND OFFICE

SURVEY

$\frac{1}{4}$

S10 | S11

1952

FROM WHICH:

10" NOW 20" HEMLOCK STUMP

BEARS S 40° E 31⁷ FT, SHOWING

A WELL HEALED BLAZE.

#54 ✓
#

PAGE 1

G.S. File No. 56/49-5 c

DIETZGEN NO. 385-5

A 40" FIR STUMP BEARS S 12° W

35° FT, SHOWING A WELL-HEALED

BLAZE.

SET A STEEL FENCEPOST WITH SURVEY

MARKER SIGN ATTACHED ALONGSIDE THE

BRASS CAP.

NEW BEARING OBJECT

A BOAT SPIKE DRIVEN IN THE TOP
OF A 60" D. FIR STUMP, DIRECTLY

ABOVE ITS ROOT COLLAR, MARKED

WITH A "10" BEARS N 76° W

26⁷ FT.

THIS CORNER LIES ON A STEEP NORTH

SLOPE NEARLY AT THE BOTTOM OF

IN A CLEAR CUT UNIT.

A CANYON 3-19-74

C. S. File No. 56/49-5 PETER L. EARLE

Larry Langley

OK
JLL