

6-4-74

16/15
21/22

T 325 RIW

Fd:

ONE BEARING TREE REMAINING, ALL OTHER BEARING TREES AND THE BRASS CAP HAVE BEEN DESTROYED BY CONSTRUCTION OF A SKID TRAIL.

THE CORNER POINT, LOCATED AT RECORD BEARING AND DISTANCE FROM THE NE BEARING TREE MARKED BY CADASTRAL ENGINEERS IN 1955:

A 13' NOW 16" D. FIR BEARS N 59° 48' E
24 ⁴/₁₆ FT., WITH SCRIBING "325 RIW
S 15 BT" VISIBLE ON PARTIALLY HEALED BLAZE.

FALLS ON A STEEP DIRT CUTBANK.

WE SET A BRASS CAP AS A WITNESS CORNER, 30 ⁰/₁₆ FT NORTH OF THE TRUE CORNER.

PAGE 1

C. S. File No. 56/51-16

#56 ✓

F. E. DARLING SON
TACOMA WASH. U.S.A.

Pat. in the U.S. & Foreign Countries
EATHEWROOF

N. 312

THE BRASS CAP IS MARKED:

COUNTY SURVEYOR'S OFFICE

T32S R1W

WIT. COR.

S16 / S15

S21 / S22

30 FT. SOUTH

TO COR.

1974

WE MARK THE FOLLOWING BEARING TREES
FOR THE WITNESS CORNER:

13" D. FIR BEARS N 82° W 9° FT.,
SCRIBED "WC T32S R1W S16 CS BT"

36" D. FIR BEARS N 53° E 55° FT.,
SCRIBED "WC T32S R1W S15 CS BT"

6-4-74

Gary Langley
PETE L EARLE

OK
JHL