

6-17-74

15/14

TZAS RIW

1/4

FD

A STONE, 16" X 12" X 10", LOOSELY SET,
WITH A FAINT "1/4" CHISELED ON A FACE,
POINTING GENERALLY WEST.

ALSO FIND A 30" NOW 32" D. FIR SHOWING
A GOOD SCAR. SINCE IT APPEARS THAT THE
ORIGINAL STONE HAS BEEN DISTURBED, WE
OPEN THE B.T. AND FIND GOOD SCRIBING.

AT THE CORNER POINT AS DETERMINED AT
RECORD BEARING AND DISTANCE FROM THE
ONLY REMAINING BEARING TREE, A 30" NOW
32" D. FIR BEARING S 41° E 17 1/2 FT., WE
SET A BRASS CAP, FLUSH WITH THE GROUND
MARKED:

COUNTY SURVEYOR'S OFFICE

TZAS

SIS SIC

1/4

RIW

WE PLACE BASALT CORNER STONE ALONGSIDE
BRASS CAP AND MARK THE FOLLOWING BT'S:

A 8" CHINQUAPIN BEARS N $1\frac{1}{2}^{\circ}$ W 32 $\frac{1}{2}$ FT,
SCRIBED " $\frac{1}{4}$ S 15 CS BT " .

A 16" HEMLOCK BEARS N $78\frac{1}{2}^{\circ}$ W 72 $\frac{3}{4}$ FT,
SCRIBED " $\frac{1}{4}$ S 15 CS BT " .

6-17-74

Gary J. Langley

PETER L. EARLE

CLEW E. GOODWIN

OK JLR