

1-13-75

18 | 17 T215 R11W

1/4

(SEE PLAN # 13)

Fo 1

1/4" I. PIPE, FIRMLY SET AND IN  
GOOD CONDITION (SEE SURVEY BY H.S.  
HUGILL, CS 40/169)

FROM WHICH:

AN 8" NOW 12" ALDER MARKED BY HUGILL  
BEARS S 18° W 11 <sup>5</sup>/<sub>8</sub> FT., ALIVE AND  
WELL-HEALED.

WE FIND NO IDENTIFIABLE REMAINS OF  
HUGILL'S NE BEARING TREE.

WE LEAVE THE CORNER MONUMENT INTACT  
AND MARK THE FOLLOWING BT.

A 12" RED CEDAR BEARS S 75° E 38 <sup>8</sup>/<sub>8</sub>  
FT., SCRIBED " 1/4 S 17 CS BT".

COMPASS DECLINATION SETTING: 20° EAST

U. C. GARBER  
NO. 10061116

#17 ✓

C. S. File No. 5717

1-13-75

Larry L. Langley

DIETZGEN NO. 385-6

S 75° E

47<sup>6</sup> @ 35<sup>1</sup>/<sub>2</sub>° .81412 38<sup>10</sup>

12" RED CEDAR