

2-12-75

$\frac{1}{4}$ $\frac{28}{33}$

T233 R9 W

(SEE REN. # 19)

FD:

ORIGINAL NE BEARING TREE, A 20" D FIR, NOW
A 30" SNAG, WHICH WE OPEN AND FIND
GOOD SCRIBING "BT"

THE ORIGINAL SW BEARING IS DOWN AND DOWN-
HILL FROM ITS ORIGINAL POSITION. WE FIND GOOD
SCRIBING " $\frac{1}{4}$ " ON A PREVIOUSLY OPENED BLAZE

AT THE CORNER POINT WE FIND A $\frac{5}{8}$ " x 60" IRON
ROD EXTENDING 2 $\frac{3}{4}$ FT. ABOVE GROUND (SEE
REN. # 19)

AT THE CORNER POINT, WE SET A 1" x 30" IRON
PIPE WITH BRASS CAP ATTACHED, MARKED:

72 ✓

PAGE 1

G.S. File No. 57/17-18 C

48" D. Fir STUMP

BRIDGE SPIKE

27° @ 20°

N 52° E

.88295

23 ⁸/_—

TOP OF STUMP ABOVE CENTER OF ROOT COLLAR

38" D. Fir STUMP

BRIDGE SPIKE

75° @ 17°

N 29° W

.9563

72 ⁶/_—

C = 0

T. 233

$\frac{1}{4} \frac{528}{533}$

R 9 W

1975

NEATHERPROOF

WASH DC

COUNTY SURVEYOR'S OFFICE

T235

$$\frac{1}{4} \begin{array}{r} 528 \\ \hline 533 \end{array}$$

R9W

1975

AND PLACE IRON ROD ALONGSIDE BRASS CAP,
FROM WHICH:

AN ORIGINAL 20" FIR, NOW A 30" SNAG BEARS
 N 15° E 31°. WE OPEN AND FIND GOOD
 SCRIBING "BT".

WE NOTE THE FOLLOWING BEARING OBJECTS:

A BRIDGE SPIKE DRIVEN IN THE TOP OF A
 48" FIR STUMP, DIRECTLY ABOVE THE CENTER
 OF IT'S ROOT COLLAR BEARS N 52° E
 23 ⁸/₁₀ FT.

AND A BRIDGE SPIKE DRIVEN IN THE TOP OF A
 38" FIR STUMP, DIRECTLY ABOVE IT'S ROOT
 COLLAR BEARS N 29° W 72 ⁶/₁₀ FT.

WE PLACE A STEEL FENCEPOST WITH SURVEY
MARKER SIGN ATTACHED APPROX. ONE FOOT
EAST OF THE CORNER.

NOTE:

THIS CORNER LIES IN A CLEAR-CUT UNIT
IN DENSE BRUSH AND LOGGING DEBRIS ON A
NORTH WEST FACING SLOPE AND APPROX.
100 FT. SOUTH EAST OF A SMALL STREAM.

COMPASS DECLINATION SETTING: 20° EAST.

2-12-75

Mary L. Langley

PETER L. EARLE

OK
JLL