

1-27-75

$\frac{1}{4}$   $\frac{22}{27}$  T285 R7W

(SEE REV. #209)

FD:

1" IRON PIPE, BARELY BENT AND SLIGHTLY  
OUT OF POSITION, WITH BRASS CAP ATTACHED,

MARKED:

COUNTY SURVEYOR'S OFFICE

T285

$\frac{1}{4}$   $\frac{522}{527}$

R7W

1969

WE REMOVE THE MONUMENT, ADD THE  
MARKINGS "1975" TO THE BRASS CAP  
AND RESET THE MONUMENT AT THE TRUE  
CORNER POINT AS DETERMINED BY  
RECORD MEASUREMENTS FROM TWO  
BEARING TREES MARKED IN 1969 BY  
THE COUNTY SURVEYOR'S OFFICE.

A 6" NOW 8" W. OAK BEARS S49°E  
36<sup>7</sup> FT., ALIVE AND WELL-HEALED.

# 226 ✓

DIETZGEN NO. 385-6

A 12" NOW 15" PINE BEARS N 42° W 66<sup>2</sup> FT,  
ALIVE AND WELL-HEALED.

NOTE:

THIS MONUMENT IS LOCATED IN AN OPEN  
PASTURE AND IS SET NEARLY FLUSH  
WITH THE GROUND SURFACE.

COMPASS DECLINATION SETTING: 20° EAST

1-27-75

Larry L. Langitz

JOHN E. NORDLING

*John E. Nordling*