

1-30-75

NE COR DLC 38

T23 S R 8 W SEC. 2

(SEE REN. # 7)

FD:

12' ROUND POST AT FENCE CORNER AND TWO BEARING TREES MARKED IN 1957 BY STATE BOARD OF FORESTRY, BOTH ALIVE AND WELL-HEALED AND LOCATED AT THE POSITIONS INDICATED IN RENEWAL # 7.

WE DO NOT CHECK FOR EVIDENCE OF THE ORIGINAL BEARING TREES AT THIS TIME AS OUR PURPOSE FOR VISITING THIS CORNER IS TO REMOVE THE PRINTED CEDAR POST NOTED IN REN. # 7 TO ALLOW FOR WIDENING OF THE COUNTY ROAD.

WE REMOVE THE ABOVE MENTIONED CEDAR POST AND NOTE THE FOLLOWING MEASUREMENTS TO AN ADDITIONAL BEARING OBJECT:

#109 ✓

C. S. File No. 52117-26

PAGE 1

C

~~250~~ 250² @ 3° .9986 250²

LOUGHS CO SUPERMARKETS OFFICE

U-50 ~~250~~ 1972

571°E

161³ @ 3° .9986 161³

A BRASS CAP, MARKED:

DOUGLAS CO. SURVEYOR'S OFFICE

U-50

1972

SET IN A CONCRETE-FILLED MONUMENT ALONG
THE NORTHERLY EDGE OF COUNTY ROAD #203
(WELLS ROAD) BEARS $S 71^{\circ} E$ $161 \frac{1}{2}$ FT.

COMPASS DECLINATION SETTING: 20° EAST

1-30-75

Gary A. Anglet

JOHN E. NORDLING

OK
JEN