

7-1-75

$\frac{1}{4}$
S | 4 T255 R5W

(SEE REN. # 26)

FD:

AN AXLE SET FLUSH IN THE GROUND
APPROX ONE FOOT SOUTH OF A FENCE
CORNER OF FENCES RUNNING NORTH,
SOUTH, AND EAST.

FROM WHICH:

A 14" NOW 32" I. CEDAR BEARS S 70° E
60 $\frac{7}{8}$ FT,

AND A 8" NOW 20" B. OAK BEARS S 12° W
37 $\frac{6}{8}$ FT.

WE FIND NO ORIGINAL EVIDENCE.

THIS CORNER LIES APPROX. 50 FT. EAST OF
A FARM HOUSE.

7-1-75

Larry J. Langlet
CLEW. E. GODDWIN

A. V. CANGIE

C. S. File No. 57/34-M LENOVA LADIG

DIETZEN NO. 385-6

OK
JHL

125 ✓