

12-2-75

T293 RBW

$\frac{17}{20} \frac{16}{21}$

(SEE REN. # 74)

FD:

1958 DOUGLAS CO. SURVEYOR BRASS CAP
OUT OF THE GROUND.

WE FIND THE FOLLOWING BEARING TREES:

WE FIND THE THREE ORIGINAL BT'S AS NOTED
IN REN. # 74. THEY OCCUPY THEIR RECORD
POSITIONS.

WE ALSO FIND THE FOLLOWING 1958 COUNTY
SURVEYOR BT'S

A 12" NOW 18" W. FIR BEARS $S 76\frac{1}{2}^{\circ} E$
 $30\frac{1}{2}$ FT., ALIVE AND WELL-HEALED.

A 6" NOW 8" YEW BEARS $S 64^{\circ} W$ 35 FT.,
ALIVE WITH SCRIBING VISIBLE ON PARTIALLY-
HEALED BLAZE.

#161

C. S. File No. 5732-23

PAGE 1

AN 8" NOW 11" YEW BEARS N 56 $\frac{1}{2}$ ° W

49 $\frac{1}{2}$ FT., ALIVE WITH SCRIBING VISIBLE ON
PARTIALLY-HEALED BLAZE.

THE NE BEARING TREE IS DOWN.

AT THE CORNER POINT AS DETERMINED FROM THE
ABOVE MENTIONED BEARING TREES, WE RESET
THE 1958 COUNTY SURVEYOR'S BRASS CAP,
A 1" X 30" I. PIPE MARKED:

COUNTY SURVEYOR'S OFFICE

T 295 R 8 W

S 17 | S 16

S 20 | S 21

1958

WE ADD THE MARKINGS "CS 1975" TO THE
MONUMENT AND MARK THE FOLLOWING NEW
BEARING TREE:

A 6" D. FIR BEARS N 26° E 14 $\frac{1}{2}$ FT., SCRIBED
"T 295 R 8 W S 16 CS BT" ON A DOUBLE BLAZE

C. S. File No. 57/39-23

31^B@ 18° 9511

30²

51^L@ 19° 9455

48³

NEW BT

6" D. Fir

N 26° E 14⁶ LVL

" T295 R6W S16 CS 2T"

1¹⁶ TACK

2⁸⁰

NOTE:

A 4" X 4" WOODEN POST, PAINTED WHITE,
IS LOCATED APPROX. ONE FOOT EAST OF
THE CORNER.

THE CORNER IS LOCATED ACROSS A SMALL
DRAW AT THE SE CORNER OF THE CAMAS
VALLEY DISPOSAL SITE.

COMPASS DECLINATION SETTING: 20° EAST

12-2-75

Larry L. Langley

CLELL E. GOODWIN

M. LENORA LADIG

A. VIC CANGIE

OK
JLD