

12-18-75

T 305

R	12	7	R1W
W	13	18	

(SEE BEN. # 35 IN T305 R2W)

FD:

A STONE, FIRMLY SET, 18" X 10" X 5" IN SIZE,
MARKED WITH 4 NOTCHES ON THE SOUTH SIDE
AND AT LEAST 1 NOTCH ON THE NORTH;

MARKHAM'S 1958 $\frac{3}{4}$ " X 24" I. PIPE IS SET
ALONGSIDE THE STONE, FROM WHICH TWO
REMAINING ORIGINAL BEARING TREES ARE LOCATED
AS FOLLOWS:

AN ORIG. 15" NOW 22" D. FIR, ALIVE AND
WELL-HEALED BEARS S 44° W 23⁰ FT.,
(REC. S 48° W 23⁰ FT.)

AND AN ORIG. 6" NOW 17" D. FIR, ALIVE AND WELL-
HEALED, BEARS N 34° W 20⁰ FT.,
(REC. N 30° W 20⁰ FT.)

A 15" NOW 35" SUGAR PINE MARKED DURING A
SUBSEQUENT GOVERNMENT RESURVEY,

#193-130-2
#198-130-1
C.S. No. 3-139-42

PAGE 1

SW

25^B @ 23° .9205

23⁷

S 44° W

PINE

26^B @ 20° .9397

25²

~~25^E~~ 26² @ 10° .9848

25⁶

NEW BT 5 "D. FIR

S 68° E

34^B @ 22° .9272

32³

~~SW~~ \$18 ~~CS BT~~

NW

22⁵ POST

30

ALIVE AND IN GOOD CONDITION, BEARS N 18° E
25 ⁷ FT.

BEARING TREES MARKED BY MARKHAM IN 1958 ARE
LOCATED AS FOLLOWS:

A 5" NOW 7" CHINQUAPIN ^{ALIVE,} SCRIBING VISIBLE ON
ROTTING FACE, BEARS S 88° W 17° FT.,
(REC. N 87° W 17° FT.)

AN A 5" NOW 6" CHINQUAPIN, IN POOR CONDITION, SCRIBE
VISIBLE, BEARS N 72° W 25 ^B FT. (REC. N 69° W
25 ^B FT.)

AT THE CORNER POINT, WE SET A 1" X 30" I. PIPE,
26" IN THE GROUND, WITH BRASS CAP ATTACHED,
MARKED:

DOUGLAS CO. SURVEYOR

T 30 S

R	S 12	S 7	R
2			1
W	S 13	S 18	W

1975

C.S. File No. ~~57/39~~ - 42

WE PLACE THE CORNER STONE ON THE EAST AND
 MARKHAM'S PIPE ON THE WEST SIDE OF THE
 BRASS CAP; AND MARK THE FOLLOWING
 BEARING TREE:

A 5" D. FIR, SCRIBED "NW S 18 CS BT"
 ON A DOUBLE BLAZE, BEARS S 68° E
 32 ³/₄ FT.

COMPASS DECLINATION SETTING: 2° EAST

12-18-75

Gary L. Langlet

CLELL E. GOODWIN

A. VIC CANGIE

M. LENORA LADIG

[Handwritten signature]

C. S. File No. 57/39-42