

PUBLIC LAND CORNERS

FILED
RECEIVED

JUN 3 1981

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

WEYERHAEUSER COMPANY

SPRINGFIELD BRANCH

TOWNSHIP 235

RANGE 2W

SECTION 36

CORNER S 1/4

COUNTY Douglas

OREGON

Weyerhaeuser Company Survey Record, 10/20/1966 by Glen McChesney and H.E. Case found of the 1894 GLO Accessories:

Stone - Found

12" Hemlock N64W 10 lks., 6.6' - found a 10" Hemlock, scribing visible, N67W 4.8' to face.

10" Hemlock S6W 25 lks., 16.5' - found a 9" Hemlock, scribing visible, S6E (record S6W) 17.5'

Referenced stone as corner point with "W" nails & plates on:

36" Fir N77W 6.1'; 38" Fir S3E 12.6'

Weyerhaeuser Company field check by G. McChesney 10/29/1969 found Douglas County Brass Cap with original stone alongside, the Brass Cap 2' east of the stone location in 1966.

Observed original Hemlock BTs were re-scribed. Removed 1966 W.Co. plates & re-referenced same trees & W nails with new bearings & distances:

36" Fir N73W 7.6'; 38" Fir S3W 11.7'

On 2/18/1981 I did not find the brass cap or the original stone, the corner point fell under a large imbedded Fir slab. Hemlock BTs OK. W.Co. reference to SW OK, but the W.Co. NW reference now a stump with "W" nail & plate both removed by logging.

Glen McChesney
Weyerhaeuser Co
Feb. 18, 1981

(County Clerk
rec'd & recorded)