

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY

SPRINGFIELD BRANCH

TOWNSHIP	23S	RANGE	4W
SECTION	33	CORNER	NW
COUNTY	Douglas	OREGON	

Douglas County Survey Record, H. L. Eppstein, County Surveyor, 8/4/1932:
Set corner from 1 old BT. Reset with 7/8"x30" Iron Bar from which an
18" White Oak N9E 90.0' and a 30" Cedar S28E 240.7'.

Douglas County Survey Record, Milo E. Godfrey, Deputy County Surveyor in
1963 found a 42" Cedar S28E 240.7' with visible scribing, and 30" White
Oak N90E90.0' with 2 good scars visible, not opened. Did not find Iron
Bar set by Eppstein. Set a Douglas County Brass Cap and scribed 1 new BT:
13" Ash S28W 18.3'. Corner falls in fence corner, fences to North, South
and East.

Weyerhaeuser Company Survey Record, 4/5/1976, by Glen McChesney. Found
the Douglas County 1963 Brass Cap at fence corner, N28E 18.3' from a
scribed 16" Ash. Also, observed, but did not measure to a 42" Incense
Cedar, with visible scribing S28E approximately 240', and a forked 30"
White Oak, faces completely healed over N11E approximately 90'.

Made 1 corner reference, with W Nail and plate on: 14" Douglas Fir S54E 91.6".

Work Done For Weyerhaeuser Company

Under The Supervision of:

By: Glen McChesney

Date 4/5/1976



Frank O. Williams

