

FILED
RECEIVED *VR*
DEC 22 1980

PUBLIC LAND CORNERS
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE
SPRINGFIELD BRANCH

WEYERHAEUSER COMPANY

TOWNSHIP 25S
SECTION 14
COUNTY Douglas

RANGE 2W
CORNER E $\frac{1}{4}$
OREGON

GLO Survey Record 1900

Stone 20 x 10 x 6 marked $\frac{1}{4}$

1. 36" Fir N54E 12 lks, 7.9'.
2. 14" Hemlock N58W 18 lks, 11.9'.

Present condition 4/5/1977

Not found.

44" Fir N54E 9.2' face overgrown

16" down, rotted Hemlock.

V. W. Hosford Survey Record 12/30/1953
Original corner stone not found but
found the 2 original BT's standing, the
Hemlock BT in Sec. 14 dead, the other
living. The corner was reset from the
BT's. (Note: There is no mention of
remonumentation accessories in
this 1953 Survey Record. -- G Mc).

V. W. Hosford Survey Record - 1957

** 25*
from the original BT's drove 1 $\frac{1}{2}$ "

200
Iron Pipe from which a new BT

3. 24" Hemlock N28W 26.6'.

Found iron pipe (alongside GLO Brass Cap).

24" Hemlock, scribing visible N28W 26.6'.

GLO Survey Record 1962

Found Hosford's 1967 1 $\frac{1}{2}$ " Iron Pipe
from which the original BT's:

G. S. File No. 58/B-35

#113 ✓

CONTINUED

PUBLIC LAND CORNERS - Weyerhaeuser Company - Springfield

CORNER:

E $\frac{1}{4}$ Corner , Sec. 14, T25S, R2W

1. 44: Fir N54E 14 1ks (Record 12 1ks).

As above

2. 16" Hemlock snag N58W 19 1ks.

As above

(Record 18 1ks.).

and tree marked by Hosford:

3. 22" Hemlock N30 $\frac{1}{2}$ W 40 1ks.

As above.

Set Brass Cap from which

Found Brass Cap

a new BT:

4. 11" Hemlock N66 $\frac{1}{2}$ W 36 1ks, 23.8'.

12" Hemlock N66W 23.8', scribing visible.

Reset Hosford's pipe alongside Brass Cap.

Weyerhaeuser Company Survey Record by

R. P. Bowers, L. Warren 3/29/1967.

Found of 1900 GLO BTs:

1. 40" Fir N53E 7.0 face overgrown.

As above.

2. 14" Hemlock snag N56W 11.5'

As above.

Found 1962 Brass Cap and BT:

8" Hemlock N65W 22.6' scribing

As above

referenced with Weyerhaeuser Company

plates and W Nails on:

1. 40: Fir N53E 7.0'.

Plate OK; W nail overgrown.

4. 8" Hemlock N65W 22.6'.

Plate and W Nail OK.

New references added 4/5/1977

5. 40" Fir S32E 15.7'.

6. 58" Fir stump S10W 26.3'.

By: Glen McChesney for Weyerhaeuser Co.

Under the Supervision of:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Frank O. Williams

OREGON
JULY 12, 1968
FRANK O. WILLIAMS
0875

G. S. File No. 58/B

1962
B.M.
B.C.

FILED
RECEIVED *JK*
DEC 22 1980
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.