

WEYERHAEUSER COMPANY
Southwest Oregon Region
Preservation of corner common to
Sections 34 & 35, T25S, R9W, W.M. and
Sections 2 & 3, T26S, R9W, W.M.
Douglas County, Oregon
September 25, 1981

FILED
RECEIVED *JS*
OCT 20 1981
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

Said corner falling on the centerline of a proposed logging spur, and with the possibility of existing accessories being obliterated by the road construction, new accessories were established as follows:

Found: 1" iron pipe, from which *#17 T26-9*
36" fir OBT bears N43°00'W 55.6 ft.
28" cedar OBT bears S23°00'W 24.2 ft.

Established: from said corner,

28" white fir scribed BT bears N19°30'E, 68.2 ft.
20" fir scribed BT bears S42°30'E, 87.3 ft.
18" cedar scribed BT bears S36°00'W, 36.6 ft.

Respectfully submitted

Michael S. McDowell

Michael S. McDowell
P.L.S. 1032

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Michael S. McDowell

OREGON
AUGUST 22 1975
MICHAEL S. MCDOWELL
1032

#22 T26-9 +
#13 T25-9 +

S. File No. *58/B-46*