

FILED
RECEIVED *JL*
DEC 22 1980

PUBLIC LAND CORNERS

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.
SPRINGFIELD BRANCH

WEYERHAEUSER COMPANY

TOWNSHIP 26S

RANGE 2W

SECTION 8

CORNER C₄

COUNTY Douglas

OREGON

Survey Record

Present Condition 1/17/1977

Marvin C. Ramsey RS404 3/1960 *20*

Set 1 1/2" Iron Pipe

1) 14" Maple N19E 59 Lks. 38.9'

2) 14" Maple S58E 60 Lks 39.6'

3) 12" Cedar N07W 123 Lks. 81.2'

4) 14" Madrone S10W 18 Lks. 11.9'

Found in place

14" Maple, scribing visible

14" Maple stump, scribing visible;

Weyerhaeuser plate & W nail intact.

12" Cedar, scribing visible; Weyerhaeuser plate and W nail intact.

14" x 20' Madrone snag, bark scribed;

Weyerhaeuser plate & W nail intact.

Weyerhaeuser Company Survey Record

H. E. Case, L. Warren 6/30/1967

Found 1 1/2" iron pipe with small brass disc on top marked RS 404.

Scribing visible on:

1) 14" Maple N19 1/2 E 37.8'

2) 14" Maple Schoolmarm S58E 38.6'

3) 12" Cedar Schoolmarm N06W 81.2'

4) 14" Madrone Schoolmarm not recorded

Pipe found - disc gone

As above.

As above.

As above.

As above.

Referenced W nails and plates on:

1) 14" Maple S58E 38.6'

As above.

#117 ✓

CONTINUED

PUBLIC LAND CORNERS - Weyerhaeuser Company - Springfield

CORNER:

C₄ Sec. 8, T26S, R2W

Cont'd

2) 14" Madrone S10W 11.0'

As above

3) 12" Cedar N06W 80.6'

As above

Accessories Added This Date by Glen McChesney

1/17/1977:

Declination 20°E

W Nails and plates on:

5) 62" Fir S88E 17.6'

6) 38" Fir N27E 43.0'

This corner is approximately 65' West and 350' South of Weyerhaeuser Company's 250 Road. The timber surrounding this corner will be logged soon.

Work done for Weyerhaeuser Company by:

Glen McChesney 1/17/1977

Under the supervision of:

Frank O. Williams RPLS 0875

REGISTERED PROFESSIONAL LAND SURVEYOR

Frank O. Williams

OREGON
JULY 12, 1966
FRANK O. WILLIAMS
0875

FILED
RECEIVED

DEC 22 1980

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.