

PUBLIC LAND CORNERS

FILED
RECEIVED *JK*
DEC 22 1980
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

WEYERHAEUSER COMPANY

SPRINGFIELD BRANCH

TOWNSHIP 26S
SECTION 8
COUNTY

RANGE 2W
CORNER NW 1/16
OREGON

Baughman Survey Record	Present condition 1/17/1977
Transit survey for Weyerhaeuser Company May 1975.	
Set 5/8" Iron rod	Found in place
1) 7" Cedar N71E 9.0'	No trace; destroyed by logging.
2) 18" Madrone S41E 37.9'	Found Madrone root wad with 18" x 5' stump, scribing visible, moved by logging and now bears S89E, 45.0'.
Weyerhaeuser Company Survey Record by Glen McChesney under the supervision of F. O. Williams, RPLS 0875 7/14/1975	
Found Baughman's 5/8" iron rod	As above
Found scribing on:	
1) 7" Cedar N71E 9.0'	As above
2) 18" Madrone S46E (Record S41E) 37.9'.	As above
Referenced with W nails and plates:	
Declination 20°E	
3) 40" Fir N40E 34.5'	40" Fir stump, W nail intact, renewed battered plate with same bearing and distance.

CONTINUED

PUBLIC LAND CORNERS - Weyerhaeuser Company - Springfield

CORNER:

NW 1/16 Sec. 8, T26S, R2W

Cont'd

4) 28" Fir S82W 21.5'
plate only on Baughman BT's:

- 1) 7" Cedar N71E 9.0'
- 2) 18" Madrone S46E 37.9

No additional references made.

Work done for Weyerhaeuser Company by:
Glen McChesney 1/17/1977.

28" Fir, W nail and plate intact

As above

As above; plate intact.

Under the supervision of:

F. O. Williams RPLS 0875

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Frank O. Williams

OREGON
JULY 12, 1968
FRANK O. WILLIAMS
0875

FILED
RECEIVED *JK*
DEC 22 1980

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

C. S. File No. 58/B-52