



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

District Office
P. O. Box 10226
Eugene, Oregon 97401

IN REPLY REFER TO:

F:RJW

OCT 7 1974

Douglas County Surveyor
Court House
Roseburg, Oregon 97470

Gentlemen:

Enclosed find a "Report on Corners of the Cadastral Survey Grid" referring to the S $\frac{1}{4}$ corner of Sec. 31, T. 19 S., R. 7 W., which is on the Lane County - Douglas County line.

The two bearing trees at this corner were cut on a recent timber sale, and the resultant high stumps have been peeled, treated with a wood preservative, and capped with a metal roof.

Sincerely yours,

Wilson Bjorge
Area Manager

Encl.

REPORT ON CORNERS OF THE CADASTRAL SURVEY GRID

T. 19S R. 7W Wil Mer. Oregon State.



SYMBOLS

- ◆ Official corner found.
- ◇ Corner found, authenticity doubtful.
- Corner searched for and not found.

DESCRIPTION OF CORNER MONUMENT

BRASS CAP $\frac{1}{4}$ Sec 31
1949

DESCRIPTION OF BEARING TREES, MOUND OF STONE, ETC.

- ① DF STUMP - 32" Dia, 4ft high, peeled, treated and covered with metal roof - Tagged - bears N 30° W 9ft
- ② DF STUMP - 40" Dia, 3ft high, peeled, treated and covered with metal roof, bears N 30° E - 35.5 feet

DESCRIPTION OF LOCATION TO ENABLE RECOVERY BY OTHERS.

Corner is along cutting line, Approx 200 ft south of Rd # 20-7-5.3. Line crossing tag on Rd near SW Sec Corn.

10/4/74
(Date)

Reported by Robert J. Walter
(Signature)
Trainer
(Title)

T20-7 #30 ✓
Form 9180-23
(October 1964)
#6 (formerly 4-1226)

U. S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

~~F19-8~~ T19-7 #1 ✓ U.S. File No. 58/11-1

GPO 845-342