

FILED
RECEIVED *ry*
JUL 1 1976

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner for Section 10 (Southeast), T23S, R10W, W.M., Douglas County, Oregon.

ORIGINAL

(No evidence of original corner found)

REESTABLISHED by A. Gibson, 1972

1½" x 36" G.I.P. (missing, in recently logged area) from which a:

- 20" Fir bears N16°W 183.4 ft.; now 22" stump in place, scribes T23S R10W S10 BT visible
- 16" Fir bears N50°W 149.1 ft.; now 18" stump in place, scribes T23S R10W S10 BT RS359 visible.
- 4" x 4" x 72" WPCP bears North 2.0 ft.; found, knocked out of place by recent logging.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T23S R10W S10 S11 1976 RS359", 34 inches in ground,

Reset 4" x 4" x 72" white painted Cedar post N20°W 1.6 ft. from corner pipe. Oregon State Forestry Department metal location poster on 4" x 4" x 72" WPCP.

Dated June 14, 1976.

Restored by *Anthony J. Klosterman* under my direction.
Anthony J. Klosterman, Engineer

Present and witnessed by Rase R. Johnson

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Arnold G. Gibson
OREGON
NOV 4 1955
ARNOLD G. GIBSON
359

#98 ✓