

FILED

RECEIVED *WJ*

AUG 18 1976

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One-quarter corner common to Sections 6 and 7, T19S, R8W, W.M., Douglas and Lane Counties, Oregon.

ORIGINAL

Post (now missing) from which a:

- 20" Fir bears N12°E 25 lks.; now 28" fir with face closed and BLM tag affixed (N25°E 16.5).
- 10" Fir bears S29°W 19 lks.; now 10" snag with BLM tag affixed, exposed scribing 4S (S15°W 12.5).

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T19S R8W ¼ S6 S7 1976 RS563", 6 inches in ground, on 80% East aspect in mound of rock, and from which a:

- 18" Fir bears S50°W 8.9 ft. to face; scribed ¼ S7 BT RS563.
No trees within limits in Section 6.

Set 4" x 4" x 60" white painted Cedar post 4 ft. NE of corner pipe. Oregon State Forestry Department metal location poster on 18" fir BT.

Dated June 8, 1976

Restored by Thomas W. Ray under my direction.
Thomas W. Ray, District Engineer

Present and witnessed by Dennis O. Bryant