

FILED
RECEIVED *WJ*

MAR 5 1977

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 11, 12, 13 and 14, T22S, R11W, W.M., Douglas County, Oregon.

ORIGINAL

Stone 12" x 10" x 5" (missing, X in place on bare rock, see below) from which a:

- 8" Fir bears N 15 E 36 lks.; now 22" stump in place, face closed.
- 12" Fir bears S 29 E 100 lks; now 50" stump in place, faces closed, bearing S 39 E.
- 12" Alder bears S 80 W 60 lks; missing, point falls in slid out draw.
- 24" Alder bears N 52 W 73 lks.; missing, point falls in slide area.

RESTORATION by A. Gibson, 1961

X on bedrock for corner point (in place) from which a:

- 13" Cedar bears S 69½ W 32.0 ft.; now 17" stump in place, scribes T22S R11W visible.
- 10" Cedar bears N 33½ W 42.9 ft; missing, point falls in slid out draw.
- 30" x 5" rock ledge bears S 45 E 11.4 ft.; in place, scribes B0 X visible.

RESTORED

Set 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T22S R11W S11 S12 S14 S13 1977 RS359", 3 inches in ground, in concrete in bedrock, in place of X and from which a:

Original 50" Fir stump bears S39E 66.0 ft. to face; scribed RS359.

Oregon State Forestry Department metal location poster on original 50" Fir stump S39E 66.0 ft.

Dated February 10, 1977

Restored by *Anthony J. Klosterman* under my direction.
Anthony J. Klosterman, Engineer

Present and witnessed by James M. McIntosh
Rase R. Johnson
Dale A. Dawson

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Arnold G. Gibson
OREGON
NOV 4, 1955
ARNOLD G. GIBSON
359

#150

C