

FILED  
RECEIVED *MJ*

MAR 9 1977

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

REWITNESSED CORNER FOR STATE OF OREGON - DEPARTMENT OF FORESTRY

One quarter corner for Section 28 (west side), T22S, R11W,  
W.M., Douglas County, Oregon.

ORIGINAL

3" x 3" x 36" post 24" in ground (missing, found 1½ iron pipe  
and cap in place, see below) from which a:

- 10" Fir bears S48W 87 lks; now 37" in place, face closed.
- 8" Fir bears S23E 57 lks; now 33" in place, broken off  
at base, scribes ¼S visible on broken off portion  
of tree 1 ft. downhill.

#151 ✓

RESTORATION by A. Gibson, 1966

1½" x 36" G.I.P. with 3" bronze cap in mound of rock (in place)  
from which a:

- Creek 12" course NE, bears S23E 78.0 ft.; in place.
- 4" x 4" x 72" WPCP bears South 2.0 ft.; in place.

REWITNESSED

From above 1½" x 36" G.I.P. a:

27" Fir bears N08E 11.3 ft. to face; scribed ¼S28BTRS359.

Oregon State Forestry Department metal location poster on original  
8" Fir S23E 37.6 ft.

Dated February 10, 1977

Restored by Anthony J. Klosterman under my direction.  
Anthony J. Klosterman, Engineer

Present and witnessed by James M. McIntosh  
Dale A. Dawson

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Arnold G. Gibson*  
OREGON  
NOV 4 1955  
ARNOLD G. GIBSON  
359