

RESTORED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner for Section 26 (East Side), T22S, R12W, W.M.,  
Douglas County, Oregon.

ORIGINAL

Hemlock post (missing) from which a:

- 36" Fir bears N50°E 10 lks.; missing.
- 36" Fir bears N05°W 11 lks.; uprooted windfall.

RESTORATION by Charles A. Slang, April 28, 1910.

(Original) Hemlock post, destroyed marks on E. side (now missing) from which a:

- 60" Fir bears N23°W 11 lks.; uprooted windfall.
- 10" Cedar bears N21°W 26 lks.; now 13" by 3 ft. high stub, in place,  
scribe 1/4 visible.

RESTORATION by Lloyd D. Smith, 1969, under direction of Arnold G. Gibson.

1½" x 36" galvanized iron pipe with 3" bronze cap (found out of place in  
root wad of uprooted BT, 25 ft. downhill), from which a:

- 11" Cedar bears S66½°E 14.6 ft.; uprooted windfall.

4" x 4" x 72" WPCP bears SOUTH 1.6 ft.; found lying on ground knocked  
out of place by uprooted BT (reset as shown below).

RESTORED

Re-set above 1½" x 36" galvanized iron pipe with 3" bronze cap and re-marked  
"OREGON STATE BOARD OF FORESTRY T22S R12W 1/4 S26 1974 RS 359," 35 inches  
in ground, and from which a:

- 68" Fir bears N22½°W 35.1 ft. to face; scribed 1/4 S26 BT.
- 59" Fir bears N73°W 32.6 ft. to face; scribed 1/4 S26 BT RS 359.

Set 4" x 4" x 72" white painted Cedar post S02°E 4.8 ft. from corner pipe.  
Oregon State Forestry Department metal location poster on 68" Fir BT  
N22½°W 35.1 ft.

Dated January 7, 1975.

Restored by William E. Metcalf under my direction.  
William E. Metcalf, Engineer

Present and witnessed by Anthony J. Klosterman  
James M. McIntosh

