

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

NONE

DIAGRAM  
T31S R2W  
NW 1/16 S22  
  
PLS 536 1975

Description of corner evidence found:

NONE

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR  
*Glenn S. Daughman*  
OREGON  
GLENN S. DAUGHMAN  
536

Description of monument and accessories I established to perpetuate the original location of this corner

I set a 30 inch long, 2 1/2 inch diameter galvanized iron pipe 24 inches in the ground, in mound of stones, with 3 inch Brass Cap stamped:

T31S R2W  
NW 1/16 S22  
PLS 536 1975

BEARING TREES:

X A Cedar, 8 inch diameter bears N20°E. 23.6 feet scribed NW 1/16 S22 (BT) with brass washer stamped LS 536 nailed at BT. Blaze

A Cedar, 7 inch diameter bears N.49°W. 40.2 feet scribed NW 1/16 S22 (BT) with brass washer stamped LS 536 nailed at BT. Blaze

NOTE: Both trees have a 6 inch red band painted around tree.

CORNER lies on steep rocky East slope, immediately East of 3 foot high rock drop, approximately 450 feet East of road.

From Book # 2, page 99, Tiller Land Survey #14 - Contract #004610N.

Office of *Surveyor* County of *Douglas*  
State of *Oregon*, I hereby certify that the within instrument was filed in this office for record on the *12* day of *February*  
*Thomas P. Ingram* by *Virginia A. Yates*  
(COUNTY OFFICIAL) (DEPUTY)