

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

NONE

DIAGRAM
T31S R2W
N 1/16
S21/S22
OLS 536 1975

Description of corner evidence found:

NONE



Description of monument and accessories I established to perpetuate the original location of this corner

I set a 30 inch long, 2 1/2 inch galvanized iron pipe 26 inches in ground, in mound of stones, with 3 inch brass cap stamped:

T31S R2W
N 1/16
S21/S22
OLS 536 1975

BEARING TREES:

A Pine, 9 inch diameter bears N.28°30'W. 12.6 feet scribed N. 1/16 S21 (BT) with brass washer stamped LS 536 nailed at BT. Blaze

A Pine, 23 inch diameter bears N.72°E. 41.3 feet, scribed N 1/16 S.22 (BT) with brass washer stamped LS 536 nailed at BT. Blaze

NOTE: Both trees have a 6 inch band of Red painted around trees.

CORNER lies on gentle East slope approximately 25 feet East of center line of Ranch Road and 3 feet East of 24 inch Cedar; also approximately 55 feet North of North and East fence corner.

From Book # 2, page # 36, Tiller Land Survey # 14, Contract #004610N.

Office of Surveyor County of Douglas

State of Oregon, I hereby certify that the within instrument was filed in this office

for record on the 1st day of February

Frank P. Cannon by Virginia C. Yates

(COUNTY OFFICIAL)

(DEPUTY)