

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

NONE

DIAGRAM
T31S R2W
E 1/16
S15
S22
RLS #536 1975

Description of corner evidence found:

NONE



Description of monument and accessories established to perpetuate the original location of this corner

I set a 30 inch long 2 1/2 inch diameter galvanized iron pipe 26 inches in the ground, in a mound of stones, with a 3 inch brass cap marked:

BEARING TREES

T31S R2W
S15
E 1/16 S22
RLS 536 1975

A 10 inch Fir bears N26°W 33.0 feet scribed
E 1/16 S15 BT. with a brass washer stamped LS
536 nailed at Bt. Blaze

A 10 inch Cedar bears S75°W. 43.0 feet scribed
E. 1/16 S22 BT. with a brass washer stamped LS 536 nailed at BT. Blaze

NOTE:

Both trees have a 6 inch red band painted around tree.

CORNER lies on West slope at timber line.

From Book #2, page #32, Tiller Land Survey #14, Contract #004610N.

Office of Surveyor County of Douglas
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 12 day of February,
Thomas R. Ingram, by Virginia A. Yates,
(COUNTY OFFICIAL) (DEPUTY)