

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

NONE

DIAGRAM  
T31S R2W  
E 1/16 S22 ONLY  
On South Line  
1974 OLS 536

Description of corner evidence found:

NONE

Description of monument and accessories established to perpetuate the original location of this corner

I set a 30 inch long, 2 1/2 inch diameter galvanized iron pipe 25 inches in the ground, in a mound of stones, with a 3 inch brass cap marked:

BEARING TREES:

A Madrone, 9 inch diameter bears N 52°30'W. 64.6 feet scribed E. 1/16 S.22 (BT) with a brass washer stamped LS 536 nailed at BT. Blaze

T31S R2W  
E. 1/16 S22  
1974 OLS 536

A Fir, 10 inch diameter bears N.59°W. 96.2 feet scribed E. 1/26 S.22 (BT) with a brass washer stamped LS 536 nailed at BT. Blaze

NOTE: Both trees have a 6 inch red band painted around tree.

Corner lies approximately 12 feet South from East-West-North-South fence corner; also at above said corner of timber line.

From Book #2, page 28, Tiller Land Survey #14 - Contract #004610N.

Office of *Surveyor* ..... County of *Douglas* .....  
State of *Oregon* ..... I hereby certify that the within instrument was filed in this office  
for record on the *12* day of *February*.  
*Thomas L. Stinson* by *Virginia A. Yates*  
(COUNTY OFFICIAL) (DEPUTY)

