

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

NONE

DIAGRAM
T31S R2W
SE1/16 S22
1974 OLS 536

Description of corner evidence found:

NONE

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Glenn S. Baughman
OREGON
JULY 14, 1961
GLENN S. BAUGHMAN
536

Description of monument and accessories I established to perpetuate the original location of this corner

I set a 30-inch long, 2 1/2 inch diameter galvanized iron pipe 26 inches in the ground, in a mound of stones, with a 3-inch brass cap marked:

Bearing trees: T31S R2W
SE1/16 S22
1974 OLS 536
A Cedar, 10 inches diameter bears
N 50° W 20.7 feet scribed SE1/16 S22 (BT)
with a brass washer stamped LS 536 nailed at BT. Blaze

A Fir, 11 inches diameter bears S 33° W
44.6 feet scribed SE1/16 S22 (BT) with a
brass washer stamped LS 536 nailed at BT. Blaze

NOTE: Both trees have a 6-inch red band painted around tree.

Corner lies approximately 5 feet East from North-South-East-West fence corner and approximately 150 feet West from North-South draw.

From Book #2, page 27, Tiller Land Survey #14 - Contract #004610N.

Office of *Surveyor* County of *Douglas*
State of *Oregon* I hereby certify that the within instrument was filed in this office
for record on the *12* day of *February* 19*74* at *11:30* o'clock *A.m.*, (signed)
Franklin J. Sugrue by *Theresa A. Zappa*
(COUNTY OFFICIAL) (DEPUTY)