

Gov't Notes

Exterior of Township 23 South Range 12 West.

Commence the Survey on the N. boundary of this Twp.

by starting at the post cor. to Secs. 36, 21, 1 & 6

Twp. 22 & 23. S.R. 11 & 12 W. of Willamette Meridian.

Found post standing and agreeing with the field notes

furnished me by the deputy Surveyor as the new post

on the corrected line Viz:-

Maple 20 ins. dia. brs. N 67° W 50 lks. dist

" 10 " " " N 82° E 40 " "

Knowing from previous observations that it will be

impossible to run the line through the 6 miles on account

of large bodies of water and swamp. I run it on a true line

Instrument used Solar Transit.

Survey commenced,

Feb. 5, 1880

W. on true line on N bdy. Sec. 1

Var. 19½° E

Ascend mountain slopes E.

35.00 Top of mountain slopes W.

40.00 Set Cherry post 4 x 4 x 5 ft. long in ground for ¼ Sec. Cor.

from which -

A Cherry 12 ins. dia. brs. S 2° W. 20 lks. dist.

" " 6 " " " N 57° W 19 " "

Ascend mountain slopes S.E.

(28)

58/36 37-8A

Township 23 South Range 12 West.

67.50 Top of mountain descend slope W.
80.00 Set Alder post 5 x 6 x 5 ft. long in ground for Cor.
to Secs. 1, 2, 35 & 36.

from which -

An Alder 20 ins. dia. brs. N 80° E 30 lks. dist
" " 24 " " " S 25° W 90 " "
" Elder 5 " " " N 25° W 10 " "

Nothing near to mark in Sec. 1.

Mountains very rough and steep, almost too steep to chain.
Soil poor and rocky. No timber standing
Undergrowth Thimbleberry and Elk brush.

W. on N bdy. Sec. 2

Var. 19½° E

Looking ahead it will be impossible to run a line so
I offset S. 10 chs. W. 25.00 chs. S. 5 chs. W. 40.00 chs.
N. 5 chs. W. 15 chs to line then N. 10 chs. to cor for Secs.
2, 3, 34 & 35 Set crabapple post 6 x 6 x 5 ft in ground for

from which

An Alder 24 ins. dia. brs. S 61° W 42 lks. dist
Willow 4 " " " N 46° W 60 " "
An Alder 12 " " " N 32° E 202 " "

Nothing near in Sec. 2 suitable to mark. This post stands
in a barley patch of a settler by the name of Carlson.
Soil on mountains hardly none at all. In bottom near
post 1st. rate. no timber on mountain.

Feb. 6, 1880.

W. on N. bdy. Sec. 3

Var. 19½° E.

7.00 Ascend mountain covered with timber.
33.00 Top of mountain descends slopes N.W.
40.00 Set Alder post 5 x 5 x 5 ft. long in ground for ¼ Sec. Cor.

from which -

28

Township 23 South Range 12 West Will. Mer. Oreg.

An Alder 12 ins. dia. brs E. 9° W. 17 lks. dist.

" " 12 " " " S 72° W 29 " "

45.50 Intersect Lake marked an alder 10 ins. dia. for witness
Cor. No witness trees cross over on drift dist.

~~57.50~~ across 6.00

~~58.50~~ Other side ascend mountain slopes S.E.

80.00 Set Fir post 5 x 5 x 4 ft. long in ground for ~~Cor. to~~ ~~Secs.~~
Cor. to Secs. 33, 34, 3 & 4.

from which -

A Fir 18 ins. dia. brs. N 43° E 50 lks. dist.

A Cherry 8 " " " ~~E~~^S 85° E 48 " "

A Myrtle 6 " " " S 35° W 28 " "

A Fir 12 " " " N 50° W 45 " "

Land mountainous covered with dense growth of Timber
Fir, Cedar and Spruce.

N on W. bdy. Sec. 4

Var. 19 $\frac{1}{2}$ ° E.

Ascend mountain.

12.50 Top of mountain descend S.W.

40.00 Set Cedar post 4 x 4 x 4 ft. long in ground for $\frac{1}{4}$ Sec. Cor.

from which -

A Maple 12 ins. dia. brs. N 22° E 23 lks. dist.

A Cedar 30 " " " N 24° W 23 " "

44.50 Cross branch 5 lks. flows S.W. Ascend.

66.00 Top of mountain slopes S.E. Descend.

80.00 Set Hemlock post 4 x 4 x 5 ft. long in ground for Cor.
to Secs. 4, 5, 32 & 33.

from which -

An Alder 10 ins. dia. brs. N 14° W 12 lks. dist.

A Hemlock 6 " " " S 24° W 10 " "

" " 7 " " " S 45° E 8 " "

Alder 12 " " " N 17° W 35 " "

Land mountainous very heavily timbered with Spruce, Hemlock
and Fir. Undergrowth Whortleberry. Feb. 7, 1880.

30

Township 23 South Range 12 West.

W. on N. bdy. Sec. 5

Var. $19\frac{1}{2}^{\circ}$ E.

Descend mountain slopes W.

11.75 Intersect Lake set Hemlock post 5 x 5 x 4 ft. long in ground for witness Cor.

from which -

A Fir 19 ins. dia brs. S 16° E 31 lks. dist.

" " 24 " " " ^NW 2° " 20 " "

Caused flag to be placed on opposite side then run S. 200 Chs. to a point from which flag brs. N 75° W giving for distance 740 lks at -

19.50 Set Hemlock post 5 x 5 x $4\frac{1}{2}$ ft. long in ground for witness cor. from which -

AN Alder 10 ins. dia. brs. N 27° W 13 lks. dist.

" " 8 " " " S 10° E 25 " "

40.00 Set Cedar post 4 x 4 x 5 ft. long for $\frac{1}{4}$ Sec Cor.

from which

A Fir 30 ins. dia. brs N 43° W 23 lks. dist.

A Cedar 24 " " " S 76° E 13 " "

42.00 Top of mountain descend.

68.00 Intersect lake about 15.00 Chs. across.

Set Hemlock post 4 x 5 x 4 ft. long in ground

from which -

A Spruce 24 in. dia. brs. S 64° W 10 lks. dist.

A Cedar 30 " " " N 52° W 12 " "

Did not continue this line any farther.

Survey ended Feb. 15, 1880.

E. boundary re run and corrected.

N. on E. bdy, of Sec. 36.

7.00 ^{Run} Ascend N.W.

31.50 Foot of mountain enter Bute.

39.00 Johnsons creek $400'$ lks. wide course W.

40.00 Set $\frac{1}{4}$ Sec. post

from which -

A Maple 15 ins. dia. ^{10°} brs. N 20° W 28 lks. dist.

