



RICHARD L. TEMPLIN
CONSULTING ENGINEER

321 NORTHWEST A STREET
GRANTS PASS, OREGON 97526

FILED
RECEIVED *mg*

MAR 2 1976

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

REGISTERED ENGINEER OREGON
REGISTERED LAND SURVEYOR CALIF.

TEL. (503) 476-7114

February 13, 1976

SURVEY NARRATIVE

Location: S. W. 1/4 of Section 7, T. 26 S., R. 5 W., of the Will. Mer. Douglas County, Oregon.

Surveyed For: Mr. Menzie Lee Wilbur, Oregon.

Purpose: To survey and monument the Easterly boundary of the Lee property which was the easterly bank for a portion and the centerline of Camas Swale Cr. for a portion of the boundary.

Camas Swale Cr. was placed in a new channel thru channel change construction in 1966 and the old channel was filled, thus destroying the boundary line of the Lee property on the easterly side. I am able to reconstruct the old centerline by using old surveys that had the centerline documented, surveys M14-61, M14-36, and M59-21, along with a survey found in C.S. Vol. 3 Page 291 which agrees with the description of the property.

I begin this survey at a 5/8th inch diameter iron rod at the point of beginning mentioned in Vol. 111 at Page 373 of the Douglas County Deed Records, said point was re-established by the Douglas County Dept. of Public Works thru survey M59-21.

I then use the Deed description and old monuments to determine the Easterly line of the Lee property, the monuments set on this line are not to be assumed the North-South boundarys of propertys to the East.

This Survey was executed with a T16-ED Transite Theodolite and a Micro-Ranger Electronic measuring instrument.

All bearings are referred to Survey Vol. 3, Page 291 of County Survey Records and are based upon Survey M 59-21



58/91
M69-39