

March 25, 1980



Richard J. Hintz

Professional Land Surveyor

1890 N. 14th Street • Coos Bay, Oregon • 97420 • (503) 267-3806

FILED
RECEIVED *JLH*

APR 1 1980

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Description Notes

Champion International Corporation
and

International Paper Company

Sections 1, 11, 12 & 13, T 21 S, R 12 W

1. $\frac{35}{2} \frac{36}{1}$

Found broken 1 3/4" IP lying on the ground from which a 48" fir stump brs. N 78° E, 1.0 ft.

Set stamped 2" IP/Br. Cap from which:

- 14" Fir brs. N 21° 30' E, 35.0 ft. scribed
- 48" Fir stump brs. N 78° 00' E, 1.0 ft.
- 22" Fir brs. S 51° 15' E, 40.3 ft. scribed
- 12" Hemlock brs. S 13° 00' W, 40.2 ft. scribed
- 10" Spruce brs. N 50° 30' W, 53.8 ft. scribed

Note: This corner was tied in by a Bonneville Power Administration crew on Dec. 2, 1948, at which time the IP was in place. The fir was a green tree, but was erroneously called a spruce by the crew. A copy of their field notes, Index No. A49-386A, may be obtained by contacting John Sink, Dept. of Energy, P. O. Box 3621, Portland, Oregon 97208.

(Copies Attached)

2. 1/4 Corner

Found 2" aluminum pipe & 45" cedar BT stump, Renewal #17, C.S. 51/311. Durham's new BT's are gone - probably destroyed during the subsequent logging. I place an aluminum tag on a 36" fir stump which brs. S 47° W, 25.7 ft.

*#63 T21-12 x 36
#98 T20-12 x 1*

3. $\frac{36}{1} \frac{31}{1}$

Found 2" aluminum pipe, Renewal #19, C.S. 54/1

Corner Description Notes

Sections 1, 11, 12 & 13, T 21 S, R 12 W

4. $1 \frac{31}{6}$ Found Douglas County Surveyor's office IP/Br. Cap.
Renewal #18, C.S. 54/1

5. $\frac{1}{4}$ Corner Set stamped 2" IP/Br. Cap from which:
 $\frac{1}{6}$
12" Fir brs. S 31° 30' E, 45.2 ft. scribed
10" Fir brs. N 25° 00' W, 11.0 ft. scribed

X 1/30 T 21-12
X 1/30 T 21-11

6. CE 1/16 Mortared stamped Br. Cap in a sandstone outcrop from which:
Sec. 1
6" Fir brs. S 21° 00' W, 17.2 ft. scribed

7. $\frac{1}{4}$ Corner Set stamped 2" IP/Br. Cap from which:
 $\frac{2}{1}$
24" Alder brs. N 23° 30' E, 69.1 ft. scribed
18" Alder brs. South, 20.2 ft. scribed

#66x

8. CS 1/16 Set stamped 2" IP/Br. Cap from which:
Sec. 1
14" Hemlock brs. S 5° 30' E, 47.8 ft. scribed
12" Fir brs. N 19° 30' W, 21.0 ft. scribed

9. SE 1/16 Set stamped 2" IP/Br. Cap from which:
Sec. 1
16" Fir brs. South 3.5 ft. scribed
10" Fir brs. N 70° 00' W, 14.5 ft. scribed

10. $\frac{1}{12} \frac{6}{7}$ Set stamped 2" IP/Br. Cap from which:
10" Fir brs. N 54° 00' E, 15.8 ft. scribed
12" Fir brs. S 31° 00' E, 9.7 ft. scribed
10" Hemlock brs. S 39° 00' W, 38.8 ft. scribed
12" Fir brs. N 43° 30' W, 9.8 ft. scribed
Corner falls in 'Cat' Road.

11. $\frac{1}{4}$ Corner Set 2" IP/stamped Br. Cap from which:
 $\frac{1}{12}$
14" Fir brs. S 89° 15' E, 42.3 ft. scribed
14" Fir brs. N 8° 30' W, 33.9 ft. scribed

#66x

Corner Description Notes

12. $\frac{2}{11} \mid \frac{1}{12}$

#67^x

Replaced 1½" IP with a 2" IP/^{70"}stamped Br. Cap from which:

- 16" Spruce brs. N 45° 00' E, 26.2 ft. scribed
- 72" Fir (snag) brs. S 48° 00' E, 27.7 ft. orig. BT
- 14" Alder brs. S 31° 00' W, 43.8 ft. scribed
- 10" Fir brs. N 84° 30' W, 32.4 ft. scribed

13. E 1/16

✓ $\frac{2}{11}$

Set 2" IP/stamped Br. Cap from which:

- 10" Fir brs. S 45° 45' W, 6.6 ft. scribed
- 8" Spruce brs. N 18° 00' W, 2.8 ft. scribed

14. ¼ Corner

#68^x $\frac{2}{11}$

Set 2" IP/stamped Br. Cap from which:

- 18" Spruce brs. N 35° 30' E, 31.3 ft. scribed
- 12" Spruce brs. S 72° 00' W, 42.5 ft. scribed

15. $\frac{3}{10} \mid \frac{2}{11}$

#69^x

Found original 70" spruce BT (stump) with nail in face, Renewal #40, C.S. 52/91

Set 2" IP/stamped Br. Cap from which:

- 16" Spruce brs. N 14° 30' E, 51.7 ft. scribed
- 70" Spruce stump brs. N 21° 00' E (not S 21° W as per notes) 34.3 ft. orig. BT
- 50" Spruce uproot brs. S 31° 45' E, 20.6 ft. to a R.R. spike driven in the upper quarter
- 12" Spruce brs. S 35° 00' W, 69.3 ft. scribed
- 8" Spruce brs. N 9° 00' W, 47.7 ft. scribed

The 1½" IP, post and 5" spruce BT as per Renewal #40 were gone.

16. ¼ Corner

10/11

#70^x

Found original 40" fir BT (stump)

Set 2" IP/stamped Br. Cap from which:

- 10" Fir brs. S 10° 00' E, 16.0 ft. scribed
- 50" Fir stump brs. S 86° 00' W, 11.9 ft. orig. BT
- 8" Fir brs. N 29° 00' W, 13.7 ft. scribed

Corner Description Notes

Sections 1, 11, 12 & 13, T 21 S, R 12 W

Page 4

17. CE 1/16 ✓
Sec. 11 ✓
Set 2" IP/stamped Br. Cap from which:
66" Cedar brs. N 57° 30' E, 20.4 ft. to 50d nail in the face, scribed
16" Alder brs. N 27° 30' W, 24.8 ft. scribed
18. ¼ Corner #71 ✓
11/12
Set 2" IP/stamped Br. Cap (offset 3.00 ft. South) from which:
14" Fir brs. North 2.9 ft. scribed
16" Fir brs. S 44° 00' W, 14.9 ft. scribed
19. ¼ Corner ✓
12/7
Set 2" IP/stamped Br. Cap from which:
14" Hemlock brs. N 46° 00' E, 17.9 ft. scribed
18" Spruce brs. S 48° 30' W, 11.0 ft. scribed
20. S 1/16 ✓
12/7
Set 2" IP/stamped Br. Cap from which:
24" Fir brs. S 26° 30' E, 17.0 ft. scribed
18" Fir brs. S 63° 00' W, 16.1 ft. scribed
21. Witness ✓
Cor. for CS 1/16
Sec. 12
Set 2" IP/stamped Br. Cap from which:
30" Hemlock brs. S 21° 30' E, 22.7 ft. to 50d nail in the face, scribed
50" Spruce brs. N 70° 30' W, 25.9 ft. to 50d nail in the face, scribed
22. ✓ SW 1/16
Sec. 12
Set 2" IP/stamped Br. Cap from which:
12" Fir brs. N 83° 00' E, 37.8 ft. scribed
12" Fir brs. S 10° 00' E, 40.3 ft. scribed
23.

10	11
15	14

 Found Douglas County Surveyor's office IP/Br. Cap, Renewal #58, C.S. 59/46

Corner Description Notes

Sections 1, 11, 12 & 13, T 21 S, R 12 W

Page 5

24. $\frac{1}{4}$ Corn.

$\frac{11}{14}$
#12^x

Set 2" IP/stamped Br. Cap from which:

18" Fir brs. S 8° 30' E, 23.4 ft. scribed
22 " Hemlock brs. N 50° 00' W, 32.3 ft. scribed

25. E 1/16

$\frac{11}{14}$

Set 2" IP/stamped Br. Cap from which:

14" Twin spruce brs. N 77° 00' E, 3.6 ft. scribed
10" Fir brs. N 59° 30' W, 6.6 ft. scribed

26. $\frac{11}{14} | \frac{12}{13}$

#13^x

Found 3 original fir BT's (stumps)

Set 2" IP/stamped Br. Cap from which:

14" Fir brs. N 27° 30' E, 49.3 ft. scribed
16" Fir brs. S 34° 45' E, 13.7 ft. scribed
52" Fir stump brs. S 15° 00' E, 23.8 ft. orig. BT
48" Fir stump brs. S 17° 00' W, 26.4 ft. orig. BT
16" Fir brs. N 66° 00' W, 9.6 ft. scribed
50" Fir stump brs. N 16° 45' W, 73.0 ft. orig. BT
(Record N 12° 30' W, 77.9 ft.)
14" Fir brs. S 51° 30' W, 27.0 ft. scribed

27. W 1/16

$\frac{12}{13}$

Set 2" IP/stamped Br. Cap from which:

16" Hemlock brs. S 52° 00' E, 14.4 ft. scribed
14" Fir brs. N 72° 00' W, 14.7 ft. scribed

28. $\frac{1}{4}$ Corner

$\frac{12}{13}$
#14^x

Set 2" IP/stamped Br. Cap from which:

12" Fir brs. N 33° 45' E, 10.1 ft. scribed
8" Alder brs. S 22° 15' E, 17.6 ft. scribed

29. E 1/16

$\frac{12}{13}$

Set 2" IP/stamped Br. Cap from which:

50" Fir brs. S 8° 00' E, 21.9 ft. scribed
14" Alder brs. N 13° 30' W, 11.4 ft. scribed

30. $\frac{12}{13} | \frac{7}{18}$

Found Douglas County Surveyor's office IP/Br. Cap
Renewal #22, C.S. 54/110

Corner Description Notes

Sections 1, 11, 12, & 13, T 21 S, R 12 W

Page 6

31. N 1/16
13/18 Found Douglas County Surveyor's office IP/Br. Cap,
C.S. 54/110
32. ✓ NE 1/16
Sec. 13 Set 2" IP/stamped Br. Cap from which:
12" Hemlock brs. S 1° 30' W, 13.5 ft. scribed
Douglas County IP/Br. Cap 'NW Cor.' brs. S 66° 29' W,
24.72 ft.
50" Fir brs. N 34° 30' W, 40.7 ft. to 50d nail in the
face, scribed
County has used this tree for their BT, see Cor. 33 below
33. 'NW Cor.' Found Douglas County Surveyor's office IP/Br. Cap from which:
50" Fir brs. N 3° 00' W, 46.7 ft. scribed
34. ✓ CN 1/16
Sec. 13 Set 2" IP/stamped Br. Cap from which:
24" Cedar brs. S 16° 30' W, 14.3 ft. scribed
12" Hemlock brs. S 78° 30' W, 12.5 ft. scribed
35. ¼ Corner
*15^x 14/13 Set 2" IP/stamped Br. Cap from which:
16" Hemlock brs. N 63° 00' E, 20.1 ft. scribed
16" Alder brs. S 35° 30' W, 10.8 ft. scribed
36. CW 1/16
Sec. 13 Set 2" IP/stamped Br. Cap from which:
12" Twin white fir brs. S 70° 30' E, 36.1 ft. scribed
60" Cedar brs. S 23° 00' W, 81.1 ft. to 50d nail in the
face, scribed
37. ¼ Corner
13/18 Found Douglas County Surveyor's office IP/Br. Cap,
Renewal #24, C.S. 54/110
38. $\frac{13}{24} | \frac{18}{19}$ Found 2" IP, Renewals #16, 23 & 59, C.S. 54/110

Corner Description Notes

Sections 1, 11, 12, & 13, T 21 S, R 12 W

39. $\frac{1}{4}$ Corner

X $\frac{13}{24}$
#76

Set 2" IP/stamped Br. Cap from which:

22" Fir brs. N 25° 00' E, 13.4 ft. scribed

18" Fir brs. S 66° 45' W, 42.5 ft. scribed

Corner falls in 'Cat' road

40. $\frac{14}{23} | \frac{13}{24}$

#77 X

Set 2" IP/stamped Br. Cap from which:

36" Fir brs. N 87° 45' E, 162.9 ft. scribed

52" Spruce brs. S 58° 00' E, 257.2 ft. to 50d nail in the face, scribed

BT overhangs Franz Creek

41. $\frac{15}{22} | \frac{14}{23}$

Found IP/Br. Cap

Renewals #6 and 25, C.S. 55/148

42. $\frac{35}{2} | \frac{36}{1}$ T21-12
T22-12

Found Douglas County Surveyor's office IP/Br. Cap,

Renewal #29, M42-27

NOTE: All distances are taken to a 50d nail driven in the side of each BT at its approximate center, unless noted. A Champion International Timberlands aluminum location tag was attached to each BT.

Richard J. Hintz, PLS #497

March 26, 1980

