



W. B. Bird

June 14, 1977

Douglas County Surveyor
Douglas County Courthouse
Roseburg, Oregon 97470

FILED
RECEIVED *of*

JUN 23 1977

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Dear Sir:

During logging operations, the brass cap for the 1/4 Section Corner to Sections 19 and 20, T27S, R2W, W.M. was removed. After logging the corner was re-set and a additional stump scribed for bearing tree. The stump will be treated and covered.

Found: Brass cap (set by County Surveyor in 1968) *2*
16" Hemlock stump, S26°W, 28.9 feet
9" Cedar stump (Down), S42°E 30.8 feet

Set: 7" Cedar stump, N62°E, 9.4 feet
MKD. 1/4 S20, T27S, R2W, B.T.

Sincerely,

T. E. Shrum

T. E. Shrum
Engineer

TES:dj
cc: Dick Bird
Bureau of Land Management



W. B. Bird

C. S. File No. 58/146-1

C