

FILED 5
RECEIVED *R*

MAR 1 1984

OREGON CORNER RESTORATION FORM

Section 24 Township 26S Range 3W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 2-1-84

Corner Designation

S 1/4

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. Perpetuated and recorded by
James Byron, Deputy County Surveyor, in 1957

Monument(s) & Accessories Found: (Condition and Source)

- 17" Fir bears N 89° E, 3.3 Ft. Healed face (1957)
- 15" Sugar Pine bears S 78° E, 32.2 Ft. (Rec.= 31.7) Healed face (1957)
- Root crown bears S 10° E, 9.9 Ft. No scribing visible (original)
- 34" Fir bears N 10° E, 17.6 Ft. (Rec.= N 40° E, 15.2) (original)
partial bark scribing visible
- 31" trunk of a triple Cedar bears S 34° W, 74.6 Ft. (Rec.= 85.7 Ft.)
scribed: 1/4 S25 CS BT (1979 - Doug. Co.)

Monument Detail

Sketch

Found a 2 1/2" brass cap set on a 1 1/2"
I.P. (Rec.= 2" I.P.) extending 12" above
ground, and loose.

T26S R3W
1/4 24
25
1957

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Surveyor's Seal

Compass Declination 20° E
 Firm/Agency Champion
Intl. Corp.
 Address P.O. Box 1328
Roseburg, Or. 97470
 Party Chief D. Turner
 Notes D. Turner
 Witness L. Sibley

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald G. Geisler

OREGON
JULY 10, 1962
RONALD G. GEISLER
1503