

FILED
RECEIVED

AUG 10 1984

OREGON CORNER RESTORATION FORM

Section 11 Township 28S Range 8W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

County Douglas Date 8-2-84

Corner Designation

CE 1/16 Sec. 11

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Corner set in 1930 by County Surveyor

Monument(s) & Accessories Found: (Condition and Source)

Found a 1 1/4" axle with attached 5" dia. hub at the corner of
a wire fence running West & South.

Also found:

30" Fir stump, 5' tall, bears S62°E, 5.3 Ft.

Scribe marks visible

Monument Detail

Sketch

Monument Set (Procedures and Description)

Set 2 BT'S:

8" Fir bears N36°W, 7.2 Ft. Scribed: CE 1/16 S11 BT

6" Fir bears N44 1/2°E, 8.6 Ft. Scribed: CE 1/16 S11 BT

New Accessories

Location & Comments

Compass Declination 20°E

Firm/Agency Champion
International Corp.

Address P.O. Box 1328
Roseburg, Ore. 97470

Party Chief R. Geisler

Notes L. Sibley

Witness D. Turner

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald G. Geisler

RONALD G. GEISLER
1973

on film

C.S. File No. 58/146-6

X