FILED
RECEIVED

DEC 14 1984

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

OREGON CORNER RESTORATION FORM

Section 17 **Township** 25S **Range** 1W

County Douglas **Date** 11/84

Corner Designation

SE Cor. 17

X **Condition Report Only**
__ **Not Found**
__ **Renewed**
__ **Unrecorded**
__ **Surveyed In**
__ **Referenced Out**

Previous Renewals/Surveys, etc. Set by V.W. Hosford in 1960, based on original field note calls.

Monument(s) & Accessories Found: (Condition and Source)

Loose & leaning 1 1/2" I.P. extending 19" above ground
B.T. 56" Fir bears N11 1/2°W, 130.2 Ft. (rec. = 130.5 Ft.) scribing visible
B.T. 52" Fir bears S62°W, 49.62 Ft. (rec. S59° 30'W, 49.0 Ft.) scribing visible
B.T. 48" Fir snag bears N47°30'E, 67.75 Ft. (rec. 68.1 Ft.) 1960, scribing visible
Measurements taken from top of leaning pipe to the face of recorded B.T.'s

Monument Detail **Sketch**

Monument Set (Procedures and Description)

New Accessories

Location & Comments **Surveyor's Seal**

Compass Declination 19°45'E
Firm/Agency Champion International Corp.
Address P.O. Box 1328
Roseburg, Ore. 97470
Party Chief R. Geisler
Notes D. Turner
Witness

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Ronald G. Geisler
OREGON
JULY 16, 1982
RONALD G. GEISLER
1988

C.S. File No. 58/146-13