

FILED
RECEIVED

OREGON CORNER RESTORATION FORM

JUL 14 1984

Section 17 Township 25S Range 1W

County Douglas Date 11/84

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Corner Designation

NW Sec. Cor.

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. Set in 1957 by B.L.M.

Monument(s) & Accessories Found: (Condition and Source)

BLM 3 1/4" brass cap on a 2 1/2" galvanized iron pipe, extends 6" above a rock mound

B.T. 26" Fir bears N67°W, 48.13 Ft. (rec. = 48.20 Ft.) closed face 1957

B.T. 8" Chinquapin bears N49°E, 20.63 Ft. (rec. = 20.50 Ft.) scribing visible (1957)

B.T. 31" Fir bears S30°E, 44.98 Ft. (rec. = 49.50 Ft.) closed face (original)

B.T. 39" Fir bears S22°30'W, 70.43 Ft. (rec. = 71.61 Ft.) closed face (1957)

B.T. 34" Fir snag bears S40°W, 43.17 Ft. (rec. = 47.50 Ft.) rotted face (original)

Monument Detail

Sketch

T25 S
 R1W
 57 | 58
 518 | 517
 1957

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Surveyor's Seal

Compass Declination 19° 45' E

Firm/Agency Champion International Corp.

Address P.O. Box 1328 Roseburg, Ore. 97470

Party Chief R. Geisler

Notes D. Turner

Witness _____

