

DATE: 20 Sept. 1977

Condition Report Only
 Not Found
 Renewed
 Unrecorded
 Surveyed In
 Referenced Out

T 19-10
27/26
34/35

Previous Renewal #'s C.S. 53/66 #1

Monument(s) Found: (Condition and Source) BRASS CAP mkd.
COUNTY SURVEYORS OFFICE, 1964. Good
CONDITION. (BRASS CAP STAMPED IN REVERSE)

Accessories Found: (Condition and Source) Good condition

13" Hemlock brs. N29E, Dist. 70² FACE PARTIAL healed

47" D-Fir orig. brs. N58E, Dist. 35⁶

39" D-Fir orig. brs. S7E, Dist. 12⁵

39" D-Fir orig. brs. S64W, Dist. 11⁹

28" D-Fir orig. brs. N59W, Dist. 5³

scribing visible

RENEWAL

Monument Set: (Procedure and Description) NONE

New Accessories: (Description) NONE

Location and Comments:	<u>20°</u>	Compass Declination
Go USFS Road #1984	<u>U.S. Forest Service</u>	Agency
To Cattle guard on	<u>Ernesto R. Alvarado</u>	Party Chief
the East side of Mr.	<u>TIM MACE</u>	Notekeeper
FRANK Andrews Farm	<u>Gordon H. Long</u>	Witnesses
Thengo south 600ft.	<u>PAT BAYNES</u>	
Along Fence Line.		

CS 58/162-46

Dependent Resurvey of South Boundary Section 27 T19S R10W, WM

Feet

Beginning at the corner common to Sections 27, 26, 34 and 35, T19S R10W WM at which point found: Brass cap marked County Surveyor's Office, 1964; 2 5/8" brass cap welded on 2-inch galvanized iron pipe, from which four original bearing trees remain:

13" Hemlock bears N29E, Distance 90⁰ ft.
face partial healed.

47" Douglas-fir original, bears N58⁰E, Distance 35⁶ ft.

39" Douglas-fir original bears S 7⁰ E, Distance 12⁵ ft.

39" Douglas-fir original, bears S64W, Distance 11⁹ ft.

28" Douglas-fir original, bears N59⁰W, Distance 5³ ft.

scribing visible

Brass cap marked (Brass cap stamped in reverse)

