

REWITNESSED CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

Section corner common to Sections 26 and 35, (East end), T22S, R12W, W.M.,
Douglas County, Oregon.

ORIGINAL

10"x10"x3' Fir Post(missing) from which a:

32" Fir bears S57°W 17 lks.; now 58"x36" high stump in place, face closed.
28" Fir bears N67°W 33 lks.; now 38"x36" high stump in place, portion of face
exposed, no scribes visible.

RESTORATION by A. G. Gibson, 1969.

1½"x36" G.I.P. in mound of stone (in place) from which a:

44" Fir(Original) bears S57°W 11.2 ft.; see above.
34" Fir(Original) bears N67°W 21.8 ft.; see above.

REWITNESSED

From the above 1½"x36" G.I.P. a:

62"x36"high Fir stump bears N16½°W 60.4 ft. to face; scribed RS 1101.

Set 4"x4"x72" white painted Cedar post S38½°E 2.0 ft. from corner pipe.
Oregon State Forestry Department metal location poster on 62"x36" high stump
N16½°W 60.4 ft.

Also poster on 58"x36" high Fir stump S57°W 11.2 ft.

Dated December 13, 1978

Rewitnessed by James M. McIntosh under my direction.
James M. McIntosh, Engineer

Present and witnessed by Joe H. Ferguson
Steven L. Ditterick
Dale A. Anders

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Lloyd D. Smith

1101
LLOYD D. SMITH
1101

JL

11/14/2 X

58/164-30