

REWITNESS CORNER FOR STATE OF OREGON--DEPARTMENT OF FORESTRY

One quarter corner for Section 23, T22S, R10W, W.M., Douglas County, Oregon.

REESTABLISHED by A.G. Gibson, 1969

1½" x 36" Galvanized Iron Pipe 34" in ground from which a:

24" Hemlock bears S12 3/4°E 36.0 ft.; now 25" in place, (I obliterate face).

45" Fir bears N82 1/2°W 35.6 ft.; now 47" in place, face closed.

REWITNESSED MAGNETIC VARIATION 20 1/2°E

Remarked 1½" x 36" galvanized iron pipe with 3" bronze cap "OREGON STATE BOARD OF FORESTRY T22S R10W 1/4 S23 1983 LS1101", and from which a:

33" Fir bears S42 1/2°W 31.3 ft. to face; scribed 1/4 S23 BT.

4" x 4" x 72" white painted Cedar post (1969) NE 1.3 ft. from corner pipe. Oregon State Forestry Department metal location poster on 47" Fir (1969) N82 1/2°W 35.6'.

Dated September 13, 1983

Rewitnessed by James McIntosh under my direction.
James McIntosh, LSIT

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Lloyd D. Smith
OREGON
LLOYD D. SMITH
1101

FILED
RECEIVED
SEP 21 1983
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE

#9/x

C. & File No. 58764-6