

NARRATIVE TO COMPLY WITH
OREGON REVISED STATUTES PARAGRAPH 209.250

SURVEY FOR: Rogue River National Forest
P. O. Box 520
Medford, Oreogn 97501

LOCATION: Sections 28 and 29, Township 29 South, Range 4 East,
Willamette Meridian, Douglas County, Oregon.

PURPOSE: Reestablish corner monuments for the common section
corner to Sections 20, 21, 28 and 29 and the one quarter
common to Sections 28 and 29, Township 29 South, Range 4
East, Willamette Meridian.

PROCEDURE: Using the original GLO Field notes, a search of the area
recovered original bearing trees for each corner. A
search at record bearing and distance with a pipe
finder recovered the original monument at each respec-
tive corner. I proceeded to verify accessories and
remonument corners as described below.

Section corner common to Sections 20, 21, 28 and 29, Township 29 South, Range 4
East, Willamette Meridian.

At the corner location I found the following references:

- A 19 inch diameter pine stump bears ^{see note} N 8° E, 104 links distant. Scribed T on
stump and 29S R4E S21 B on log lying along side, in a single blaze.
- A 23 inch diameter fir bears S 20° E, 45 links distant with a single healed
blaze.
- A 11 inch diameter fir snag bears S 4° W 50 links distant, illegible
scribing visible on single blaze (face has been scraped by a cat).
- A 20 inch in diameter fir bears N 76° W 24 links distant with a healed
single blaze.

FILED
RECEIVED ✓
SEP 13 1979
CLERK OF THE COUNTY, ORE

From which I found the original monument lying 6 inches underground and tipped at about a 40 degree angle. I reset this monument at record distances and established the following new references:

#9 ✓
A 12 inch diameter pine bears North 107 links distant. Scribed T29S R4E S21 LS 1071 BT on a double blaze.

A 8 inch diameter fir bears S 44° 30' W 35 links distant. Scribed T29S R4E S29 LS 1071 BT on a double blaze.

The one quarter corner common to Sections 28 and 29, Township 29 South, Range 4 East, Willamette Meridian.

At the corner location I found the following reference:

A 45 inch diameter Douglas-fir with a healed single blaze.

No evidence of the original 12 inch pine could be found.

#10 ✓
At record bearing and distance I found the original GLO monument in good condition but buried 10 inches under a mound of earth.

From which I established the following reference:

A 22 inch in diameter fir bears N 31° 30' E 247 links distant. Scribed 1/4 S28 LS 1071 BT on a double blaze.

HAROLD L. CENTER
Registered Professional Land Surveyor
Oregon Certificate No. 1071



FILED
RECEIVED
SEP 13 1979
COUNTY SURVEYOR
CLATSOP COUNTY, ORE