

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

August, 1857, Hathorn

- Set Post
- 15" Fir S25°E, 30 Lks.
- 15" Laurel, N25°W, 84 Lks.

June 29, 1908, Mensch

- Set 15"x10"x5" stone
- 18" Fir S25°E, 31 Lks, "1/4 S4 BT"
- 4 " Madrone, N3½°W, 85 Lks. "1/4 S5 BT"

1966, County Surveyor

- Set Brass cap marked:
- 8" D. Fir S22°W, 10.6 ft "1/4" S5 BT"

T31S R2W
¼ S5/S4

**FILED
RECEIVED** *dh*

FEB 22 1979

1970, County Surveyor

- Destroy everything that refers to Sec. 5
- 6" D. Fir N83 1/2°E, 13.6 ft "1/4 S4 CS BT"

Description of corner evidence found:

- 1" Iron pipe on 2½" Brass cap marked as shown
Stone alongside pipe.
- 8" D. Fir N85½°E, 13.6 ft - good scar
- 28" D. Fir uproot, S28°E, 21.4 ft
- 12" D. Fir, S16 3/4°W, 10.5 ft - good scar

**COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.**



Description of monument and accessories I established to perpetuate the original location of this corner

Scribed "1/4 S4 BT" on 14" D. Fir bears N29 3/4°E 27.0 ft.
Attached 3/4" Brass Washer "LS 866" to lower blaze.

Bearings based on solar observation.
Mag. decl. approximately 21° East

Francis L. Ingram

(COUNTY SURVEYOR)

Office of County Surveyor County of Douglas
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 22 day of February, 1979, at 4 o'clock P.m., (signed)
FRANCIS L. INGRAM by Gregory E. Fitchell
(COUNTY OFFICIAL) (DEPUTY)